


# Crack & Hole Patch REFILL SHEETS

**4 Easy Steps** to repair cracks & holes

## apply in 4 easy steps



Prepare the area around the hole so that it is smooth and free from any loose material or flaking paint. Make sure the surface is clean, dry and dust free.



Cut CoverCrakZ to size, ensuring that there is approximately 50mm overlap around the perimeter of the hole.



Use a generous layer of paint to adhere CoverCrakZ to the surface and to ensure a good bond. If extra strength is needed, additional layers of CoverCrakZ may be applied using the same method.



Depending on the size of the hole, a converse indentation may result. This allows the area to then be easily filled, sanded and finally, painted to restore an as new finish.

**Safety Precautions:** CoverCrakZ may cause irritation if it comes in contact with the skin, eyes or if inhaled.

It is recommended that gloves are used when handling CoverCrakZ. For full specifications consult the

CoverCrakZ Material Safety Data Sheet at [www.reginaglass.com.au](http://www.reginaglass.com.au)



Regina Glass Fibre Pty Ltd  
P.O. Box 539, Ballarat Vic 3353, Australia  
Telephone: +61 (03) 5339 2214  
Facsimile: +61 (03) 5338 1013  
Email: [office@reginaglass.com.au](mailto:office@reginaglass.com.au)  
Web site: [www.reginaglass.com.au](http://www.reginaglass.com.au)

**REGINA**  
GLASS FIBRE TISSUE & VEIL

**CoverCrakZ**